Date of Issue:	NOVEMBER 15, 2024
Project:	CONTRACT NO. 24-3 SPRINKLER HEAD REPLACEMENT ASHLAND HIGH RISE
Project Owner:	SCHUYLKILL COUNTY HOUSING AUTHORITY 245 Parkway, Schuylkill Haven, PA 17972
Bid Due Date:	<b>NOVEMBER 19, 2024 AT 10:00 AM</b> (Local Prevailing Time) At the office of the Schuylkill County Housing Authority

Prior to submission of a bid for this project, all Contractors are urged to visit the Levkulic Associates website at www.levkulicgroup.com to view the most current information pertaining to this project.

## I. GENERAL CLARIFICATIONS:

- 1. An RFI was received from Tri Vet Contracting asking the following questions. Answers follow each question.
  - Q1: The bid SOW form indicated 296 heads. Please confirm this is the correct number of heads to be replaced.
  - A1: The number of heads were verified by the Owner's maintenance personnel. The bid form indicates "Should fewer or more heads exist, the bid form also indicates "Note: The Lump Sum Base Bid Total indicated above is based on the replacement of 296 sprinkler heads. Should additional or fewer than 296 sprinkler heads require replacement, the unit price shall be calculated as the Lump Sum Base Bid Total divided by 296 to arrive at an add/deduct price as a modification to the Lump Sum Base Bid Total. "
  - Q2: Multiple sprinkler heads in the basement are close to ductwork and storage partitions. Some of the sprinklers are located between obstructions and we will not be able to replace them unless the obstruction is removed, such as storage mesh or wood framing. Please verify who will remove these obstructions.
  - A2: Owner will coordinate temporary relocation of tenant belongings impeding access to work areas. Should building construction conditions impinge upon access to the work area, Contractor shall be responsible for access to the work area and repairs or patching to items modified to access the work area.
  - Q3: There is currently no specification sheet that details the type of sprinkler heads required to replace the GEM F950 165° chrome fusible pendant and upright sprinkler heads. Please advise on the appropriate type of heads to use for the replacement of the existing sprinklers.
  - A3: Replacement heads shall be quick response heads  $\frac{1}{2}$ " chrome.

- Q4: The sprinkler branch line located in the basement under the first-floor bathroom leak is severely corroded and we'd recommend replacement.
- A4: The branch line will be addressed via either change order or third-party vendor currently under contract with owner if needed.
- Q5: Each floor manifold is equipped with a control valve that isolates the designated floor. If the control valves are defective and unable to stop the flow of water, they must be replaced before we can begin replacing the sprinkler heads. Will change orders be permitted to address these issues as they arise?
- A5: Should valves not hold, Owner will entertain change order to repair/replace items required.
- Q6: It is my understanding that submittal drawings are not required and that only the material data sheets are necessary. Please confirm if this is correct.
- A6: Contractor shall provide material sheets only for approval.
- Q7: Please provide the latest copy of the Annual Inspection Report for the sprinkler system.
- A7: The most recent test is attached (2 pages)

# Form for Inspection, Testing and Maintenance of Wet Pipe Fire Sprinkler Systems



NN/@tz

This form covers the minimum requirements of NFPA 25-2011 for wet pipe fire sprinkler systems connected to water supplies without tanks or fire pumps. Separate forms are available for fire pumps, tanks, hose connections, and other fire protection systems. More frequent inspection, testing and maintenance may be necessary depending on the conditions of the occupancy and the water supply. The work covered on this form is (*fill-in one*): O Monthly O Quarterly O Annual O Third Year O Fifth Year Semi-Annual

Owner:		Owner's Phone Number	
Owner's Address:			
Provide Drive Directivated ASh land	Irgh Ris	<b>:</b>	
Property Address: 319 Center Street	Ashland 1	<u>4 17921</u>	
All reconnect refe	r to the current w	oric (inspection, testing and maintenance) perform	med on this date.
1) All montions and to be ensured les	Vo . or Not Annlied	the All "No" answers are to be explained in ra	IT III OI THIS IOTH.
2) Inspection, Testing and Maintenance a	re to be performe	d with water supplies (including life pumps) in s	ervice, unless the
impairment procedures of Chapter 15 of			
Part I – Owner's Section		4. Annual Inspection Items (in addition to abo	ve items)
A is the building occupied?	Yes O No	a. Proper number and type of spare sprinklers?	JI ES JINO GAN/A
B. Has the occupancy and hazard of contents	Xes O No	b. Visible sprinklers: 1. Proper position: upright, pendent, sidewall?	OYes ONo ON/A
Temamou die admo since die more in p	O Yes O No		OYes ONo ON/A
C. Are all fire protection systems in service? D. Has the system remained in service without		3. Proper clearance below sprinklers?	OYes ONo OX/A
modification since the last inspection?	Yes O No	4, Free of foreign materials including paint?	OYes ONo ON/A
E. Was the system free of actuation of devices		- 이 가장은 정치가 방법을 통했다. 이 물건이 가격하는 것 같아요. 가지 않는 것이 가지 않는 것이 같아.	OYes ONo ON/A
or alarms since the last inspection?	Yes O No	c. Visible pipe:	an an hu
m. Min. lev dellik.	by any		OYes ONo ON/A OYes ONo ON/A
Jett Welder Vor Ugue	10107	<ul> <li>2. No mechanical damage or leaks?</li> <li>3. No external loads?</li> </ul>	OYes ONo ON/A
Owner or Representative (print name) Signature as	nd Date	d. Visible pipe hangers and seismic braces	
Part II – Inspector's Section		not damaged or loose?	OYes ONo OWA
		e. Sprinkler wrench with spare sprinklers?	OYes ONo ON/A
A. Inspections 1. Weekly Items		f. Information sign is attached and legible?	OYes ONo ON/A
a. Control valves (including backflow preventer		g. Internal inspection of the pipe performed in	the
isolation valves) supervised with seals passed	1	last 5 years (remove a flushing connection a one sprinkler near the end of a branch line)?	OVer ONE ONA
inspection as described in II.A.2.a below? OYes		(If "No", conduct internal inspection	
	SONO ON/A	5. Fifth Year Inspection Items (in addition to	above items)
2. Monthly Inspection Items (in addition to above it	(CHIIS)	a. Alarm valves and associated strainers, filter	s and
a. Control valves and valves on backflow preventers with locks or electrical supervision:		restricted orifices passed internal inspection	?OYes ONo ØN/A
1. In correct (open or closed) position?	s ONo ON/A	b. Check valves internally inspected, all parts	
2. Lock or supervision in place?	s ONo ON/A	operate properly and are in good condition? c. Internal pipe inspection performed per 4.g?	OYes ONO GN/A
3. Accessible and free from external leaks? OYe	s ONo ÓNA	1. 1945년 1947년 1977년 1971년 1971년 1971년 1971년 1971	
	s ONo ON/A s ONo ON/A	B. Testing - Report any failures on Part III of	this form.
) TIUVIGGU WIGHT UPPTOPTOPTOPTOPTOPTOPTOPTOPTOPTOPTOPTOPTO	S CINU CAINA	1. Quarterly Tests	
b. Gauges on system in good condition and showing normal water supply pressure?	s ONo ON/A	a. Mechanical waterflow alarm devices passed tests (alarms actuated and flow observed?	Wes ONG ON/A
c. Alarm valve free from physical damage, trim		b. Main drain test for system downstream of t	ackflow device or
in correct (open or closed) position and no		pressure reducing valve:	
leakage from retarding chamber or drains? OYe	s ONo ON/A	1. Record static pressure 135 psi, resid	high processing / )
3 Quarterly Inspection Items (in addition to above	e i <b>tems)</b>	2. Was flow observed?	QY as ONo ON/A
a. Fire department connections visible, accessible,		3. Are results comparable to previous tests	
couplings and swivels not damaged, gaskets in place and in good condition, plugs and caps are of	kav.	2. Semiannual Tests (in addition to previous	items)
identification sign(s) in place, check valve is not l	leaking.	a. Valve supervisory switches indicate	
alaphar in place and operating properly and autop	aatic	movement?	ØYes ONo ON/A
drain value in place and operating properly? OY	S ONO ON/A	b. Electrical waterflow alarm devices passed	An ar ar
Af plugs or caps are not in place, inspect interior for	obstructions).	tests (alarms actuated and flow observed)? 3. Annual Tests (in addition to previous iter	ØYes ONo ON/A
b. Hydraulic nameplate (calculated systems)		a. Main drain test for systems not tested quar	terly:
securely attached to riser and legible?	es ONo ON/A	a thight man more to be been not as a dam	
c. Alarm & supervisory devices not damaged? dy	es Oivo Oiv/A	1. Record Staticpsl and Residual	Pressurep
d. Pressure reducing valves in open position, not lea with downstream pressure per design criteria, and	d in good	2. Was flow observed?	OYes ONo ON/
condition with handwheels not broken? OY	es ONo ON/A	3. Are results comparable to previous tests	s? OYes ONo ON/

©2013 National Fire Sprinkler Association, 514 Progress Drive, Suite A, Linthicum Heights, MD 21090 (845) 878-4200 Form 25-13W-11 Sheet 1 of 2

	Annual Maintenance Items (in addition to previous items) a. Operating stem of all OS&Y valves
ost indicating valves opened until spring or torsion	a. Operating stem of all OS& r valves lubricated, completely closed, and reopened? OYes ONo GN/A
elt in the rod then closed back 4 turns	nuoncaled, completely closed, and reopened. Cite Cite State
re all sprinklers dated 1920 of later?	b. Sprinklers and spray nozzles protecting
prinklers with fast response elements 20 years	commercial cooking equipment and ventilating
d or more replaced or successfully sample	systems replaced except for bulb-type which
OYes ONO ON/A	show no signs of grease build-up? OYes ONo QN/A
accessfully sample tested in last 10 years? OYes ONo ON/A	Part III – Comments (Any "No" answers, test failures or other
	problems found with the sprinkler system must be explained here.)
accessfully sample tested in last 5 years? OYes ONo ON/A	As a courtesy, note on a separate form any concerns about anything
Iccessfully sample tested in the	that you saw while performing your work that is not a part of the
OYes ONe ØN/A	NFPA 25 requirements including any recalled products that you
Ample residen in last to yourse	happened to notice.]
nrinklers subject to naisi environmenta reprieta et	
ICCessfully sample tested in tust of former	
ntifreeze solution specific gravity:	
L'OTTECI AL HOST ICHIOTO POINT	
Correct at interface with wet system? OYes ONo GN/A	
Correct at other test points (over 150 gal)? OYes ONo ON/A	
Correct type of antifreeze?	
il control valves operated through full range	
1. to more than a more than the second position?	1998년 1월 20일 - 1일에 관한 1 1997년 1월 20일 - 1일에 관한 1998년 1월 20일 - 1일에 관한 1 1997년 1월 20일 - 1일에 관한 1998년 1월 20일 - 1일에 관한 1
1 d destage mage of forward flow test? O'Yes O'NO O'NA	
and the second state of the second se	
and the second fin addition to appropriate news	
the stand temperature resident ( UTVO UTVO UTV)	
1 - 1 - 1 - 1 house librated care of remacculul 153 UNV 54 MA	· 그 같은 것은
ressure reducing valves passed full flow test? OYes ONo ØN/A	
laintenance	에 이 것은 것이 같은 것이 있는 것은 것이 있는 것이 있는 것이 있는 것이 있는 것이 있다. 이 이 것은 것이 같은 것은 것이 있는
milor Maintenance Items	
e for the follow the compling testing OI	
Parts II B.3.d. e. f. g or h of this form, were all sprunklers	
enresented by that sample replaced?	
committee have been replaced, were mey	
O I es O N O W A	
a manufactory and the second s	
sitial turice if raw water got into the system O 1 cs On O AMIT	
in manufacturer's instructions	
OYes ONo ON/A	
f any of the following were discovered, was	
1 4 station conducted? UICS UNU WING	
in the second advantage of the second s	
Defective intake screen on numb supplied nom open searces	
of the state in the state of th	
The statistical in dructine valves, check valves of pumps	
Foreign material in water during drain test or plugging of	
the stand compaction	
inspector's test connection Plugging of pipe or sprinklers found during activation or work	
Plugging of pipe of spillikiers tourki definity	
5. Record of broken mains in the vicinity	n an an an an an an an ann an an ann an
Abnormally frequent false-tripping of dry-pipe valves	
Failure to flush yard piping or surrounding mains tonowing	
the second se	Part IV - Inspector's Information Phone: (570)
9. System is returned to service after an extended period of time	
	Inspector: Robert Fredder Company: Harrell Automa
to believe the system contains source sincero	
1 A PARTICIPAN AND A COTTOSIVE HILLS III WURDWI PPPY	Company Address: Second and Fair St. Mifflinville, PA
or its derivatives of highly content of the fire department connection 11. Raw water was pumped into the fire department connection	I state that the information on this form is correct at the time and
12 Pinhole leaks	the time time to an that all equipment tested at this time
for the second that required	
flushing was flushing of system conducted? Oiles Oilo Oily	Was left in operating continuon upon condition of the
alored values?	Simetime of Inenector for Penan Date: (24-6
Adjusted, repaired, reconditioned or replaced	Signature of Inspector. Jack Verden Date: 127-2
and such a had the eggenciated reals allu/ul	40 111
spections performed? OYes ONO ØN/	License or Certification Number (II applicable):

Date of Issue:	OCTOBER 27, 2024
Project:	CONTRACT NO. 24-3 SPRINKLER HEAD REPLACEMENT ASHLAND HIGH RISE
Project Owner:	SCHUYLKILL COUNTY HOUSING AUTHORITY 245 Parkway, Schuylkill Haven, PA 17972
Bid Due Date:	<b>NOVEMBER 19, 2024 AT 10:00 AM</b> (Local Prevailing Time) At the office of the Schuylkill County Housing Authority

Prior to submission of a bid for this project, all Contractors are urged to visit the Levkulic Associates website at www.levkulicgroup.com to view the most current information pertaining to this project.

## I. GENERAL CLARIFICATIONS:

1. The Owner has rejected bids received on October 7, 2024 and is rebidding the project. Project information previously issued shall be utilized for rebidding purposes. Revised Invitation to Bid attached with revised pre-bid and bid opening dates attached. (2 pages).

# **INVITATION TO BID**

## SPRINKLER HEAD REPLACEMENT CONTRACT NO. 24-3

The Schuylkill County Housing Authority will receive sealed bids for work to be performed at the Ashland High Rise – PA-16-14. This project is funded by the Capital Fund Program.

Work includes: Removal of existing pendant sprinkler heads and the provision of new pendant sprinkler heads, complete and ready for use and in compliance with the latest codes and regulations.

Bidders are hereby notified that this project is subject to the Davis Bacon Federal Prevailing Wage Rate regulations and Contractors will be required to pay the prevailing wage as indicated within the schedules.

A pre-bid conference will be held on Thursday, November 7, 2024 at 10:00 A.M., local prevailing time, at the office of the Schuylkill County Housing Authority, 245 Parkway, Schuylkill Haven, PA 17972. All bidders are urged to attend the conference. Representatives of the Housing Authority and Levkulic Associates will be in attendance.

Bids will be received until 10:00 A.M., local prevailing time, on Tuesday, November 19, 2024 at the office of the Schuylkill County Housing Authority, 245 Parkway, Schuylkill Haven, PA 17972. Bids will be opened publicly and read aloud. Bids shall be submitted in a sealed envelope with the Contract Name clearly written on the envelope.

All requests for Bid Documents must be in writing, with the following information contained thereon: 1) Specific Bid Document(s) requested (Contract Name, Description, etc.), 2) Bidders name, complete street address and contact person, 3) Bidders telephone number, fax number and e-mail address.

Payment of a non-refundable service fee, in check or credit card form in the amount of thirty dollars (\$30.00), payable to Levkulic Associates, is required for each set of digital bidding documents. Only complete bid packages will be issued by the Design Professional. Bid packages will only be issued in digital format.

Plans, specifications and bidding documents may be examined and secured at the office of the Design Professional. The Design Professional of record is Levkulic Associates, Union Street Station, 101 East Union Street, Pottsville, PA 17901, Telephone: (570) 628-2887. Plans may also be requested on-line at www.levkulicgroup.com.

Addenda, if any, will be issued only to those persons whose name and address are on record with the Design Professional as having obtained the Contract Documents from the Design Professional.

A bid may not be modified, withdrawn, or canceled by the bidder for sixty (60) days after the time designated for receipt of bids.

Bid security in the amount of 10% of the bid price shall be submitted with the bid. Bid security shall be in one of the following forms only: Certified check (drawn on a bank authorized to conduct business in the Commonwealth of Pennsylvania), or bid bond. The surety must be on the latest approved U.S. Treasury List, Circular 570. The bidder will be required to submit a Certificate of Surety with the bid. The successful bidder will be required to furnish a Performance Bond and Labor and Material Payment Bond and each shall be in the amount of one hundred percent (100%) of the contract price. A one-year Maintenance Bond shall also be required. Cost of bonds to be included in the base bid.

The Schuylkill County Housing Authority is an Equal Opportunity Employer. All prospective Bidders are informed that the work covered in this Invitation to Bid is subject to the requirements of Section 3 (24 CFR Part 135). All Bidders must submit a Section 3 Plan as a part of their bid submission or their bid submission(s) may be considered non-responsive.

Each Bidder shall also comply with the following Equal Opportunity requirements:

- 1. Notice of Requirements for Affirmative Action to Ensure Equal Employment Opportunity (Executive Order 11246) 42 CFT 70.42 (d) including the goals and timetable for women (6.9%) as set forth in Appendix "A".
- 2. Standard Federal Equal Employment Opportunity Construction Contract Specifications (Executive Order 11246 41 CFT 60-4.3).
- 3. Equal Opportunity Clauses (41 CFT 60.1.4(a) and (b)).
- 4. Section 3 Clauses (24 CFR Part 135.38).

The Bid is for a Public Works Contract and the Bidder is subject to the provisions, duties, obligations and penalties of the Public Works Employment Verification Act, 43 P.S. 167.1-167.11.

The Schuylkill County Housing Authority reserves the right to reject any or all bids or to waive any technicalities and informalities in the bid for the best interest of the Housing Authority, and to consider the competency and responsibility of the Bidders in awarding the contract.

Thomas F. Hale, Executive Director Schuylkill County Housing Authority

Date of Issue:	OCTOBER 4, 2024
Project:	CONTRACT NO. 24-3 SPRINKLER HEAD REPLACEMENT ASHLAND HIGH RISE
Project Owner:	SCHUYLKILL COUNTY HOUSING AUTHORITY 245 Parkway, Schuylkill Haven, PA 17972
Bid Due Date:	<b>OCTOBER 7, 2024 AT 10:00 AM</b> (Local Prevailing Time) At the office of the Schuylkill County Housing Authority

Prior to submission of a bid for this project, all Contractors are urged to visit the Levkulic Associates website at www.levkulicgroup.com to view the most current information pertaining to this project.

## I. GENERAL CLARIFICATIONS:

1. Addendum No. 1 indicates the Bid Opening time to be 11:00 AM. Bid opening shall be October 7, 2024 at 10:00 AM at the office of the Schuylkill County Housing Authority as indicated within the Invitation to Bid and project manual references.

Date of Issue:	SEPTEMBER 19, 2024
Project:	CONTRACT NO. 24-3 SPRINKLER HEAD REPLACEMENT ASHLAND HIGH RISE
Project Owner:	SCHUYLKILL COUNTY HOUSING AUTHORITY 245 Parkway, Schuylkill Haven, PA 17972
Bid Due Date:	<b>OCTOBER 7, 2024 AT 11:00 AM</b> (Local Prevailing Time) At the office of the Schuylkill County Housing Authority

Prior to submission of a bid for this project, all Contractors are urged to visit the Levkulic Associates website at www.levkulicgroup.com to view the most current information pertaining to this project.

#### I. GENERAL CLARIFICATIONS:

- 1. The following topics were discussed at the pre-bid meeting for the project:
  - A. Temporary sanitary facilities indicated within Technical Specification Section 01 50 00 – Temporary Facilities will not be required for this project. Contractor will be permitted to utilize public toilets within the building.
  - B. Project identification sign indicated within Technical Specification Section 01 50 00
     Temporary Facilities will not be required.
  - C. Temporary heat indicated within Technical Specification Section 01 50 00 Temporary Facilities will not be required.
  - D. Field offices indicated within Technical Specification Section 01 50 00 Temporary Facilities will not be required.
  - E. As-Built Drawings indicated within Technical Specification Section 01 70 00 Project Closeout willnot be required, however, submittals, inspection and test reports, and any warranty information will be required for project closeout.
  - F. Sweeping and washing of paving areas indicated within Technical Specification Section 01 70 00 Temporary Facilities will not be required.
  - G. The project duration was discussed. Per Technical Specification Section 01 00 00-Summary of the Work, Paragraph 3.1, Contract completion time shall be 30 days.
  - H. Per the Owner, the Pipefitter wage rate included within the project manual shall be utilized as the minimum pay rate for all workers performing sprinkler head replacement work.